

FIG. 2





FIG. 2

FIG. 3



09975989-101501

FIG. 4

URL

MALFUNCTION DATABASE INPUT SCREEN

DATE OF OCCURRENCE ~ 404

MODEL ~ 401

SUBJECT MATTER ~ 403

EQUIPMENT SERIAL NO. ~ 402

DEGREE OF URGENCY ~ 405

CONDITION ~ 406


COUNTERMEASURE METHOD ~ 407

PROGRESS REPORT ~ 408

410 411 412

[LINK TO DATABASE OF RESULTS](#) [SOFTWARE LIBRARY](#) [OPERATING GUIDE](#)

FOOT" 68652660

FIG. 5

FLOW OF SEMICONDUCTOR DEVICE MANUFACTURE

FOI 6865/660

FIG. 6

